Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: JOY 26-35H

Field Name: STANLEY Well File #: 18286

Date Incident: 4/11/2016 Time Incident: 11:00 Facility ID Number:

County: MOUNTRAIL Twp: 155 Rng: 91 Sec: 26 Qtr: NW NW

Location Description:

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Gas condensate

Inspected: Written Report Received: 4/18/2016 Clean Up Concluded: 4/18/2016

Risk Evaluation:

None

Areal Extent:

Small area of grass burned off site

Potential Environmental Impacts:

None

Action Taken or Planned:

Treater pressure adjusted.

Wastes Disposal Location: None

Agencies Involved: Stanley FD, Mountrail County

Updates

Date: 4/11/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the fire was not contained to the well pad. Further follow-up needed.

Date: 4/13/2016 Status: Inspection Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 15:45. 20 mph wind from the SE, 66 degrees, mostly cloudy. Nearest water is a large wetland that lies on the east side of the facility well pad. Fire was at the treater flare. It burned an area 10 meters by 15 meters in the adjacent wheat stubble field. The fire appears to have self extinguished. Recommend revisiting in mid summer to ensure that no long-term impacts have occurred to the wheat field. Off site 16:10.